

## Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



## **WORK ORDER INFORMATION**

Work Order Name: WO/80008KN0166/1

Work Order Type: Weatherization

Audit Name: 80008KN0166-Audit

**CLIENT INFORMATION** 

Client Name:

Address:

Client ID: 80008KN0166

Alt. Client ID: KNOX

<u>AGENCY INFORMATION</u>

Agency: Knoxviile/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & Licens	se Number: _	 	 	
Contractor's Signature:				

## **COMMENT**

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

Home built in 1960

An EPA Certified Firm/Renovator is required.

Client Name:

Client ID: 80008KN0166 Alt. Client ID: KNOX

Work Order (Bid Form)

Work Order Name: WO/80008KN0166/1

Report Run On: 5/8/2010

**DOE Weatherization Assistant** 

Version 8.6.0 Page 1 of 7

## Measures

Ме	easure 1 Wi	indow Screen(E3)		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Component	ts			Inspected
Cor	verify	to house diagram with wir measurements in the field ndix A- Standards for Weat	before ord	lerina '	vindow scree	en(s). Re	efer to		
					Estimated			Actual	
# M	laterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 V	Vindows	Window Screen	Each	1					
2 L	abor	Labor	Each	1					
Oth	er Detail					-			
				Measur	e Sub Total:		] :	Sub Total:	
Flo	eld Notes:						10000	·	

Measure 2 DV	VH Pipe Insulation			Componen	ts			Inspected
Comment				·				
				Estimated	•		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
	Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail							""	
			Measur	e Sub Total:		] .	Sub Total:	
Field Notes:	7 TABLE		ru=u	***************************************	WALL	•		

Report Run On: 5/8/2010

Me	asure 3	Floor Ins. R-19			Componen	ts F1			Inspected
Con	bef Sta sub (e.ç con	cludes labor cost. Cor ore installing insulation ndards. Insulation is ifloor above (paper si g. staves for blankets) npressions. Refer to l Southeast Field Guid	n. Contractor to i installed to maint de against subflo . Insulation to ha Appendix A- Star	nstall u ain per or) incl ove NO	sing Resnet manent cont uding necess gaps, voids,	Grade 1 act with the sary support	ne orts		
					Estimated			Actual	<del></del>
# Ma	aterial / Lab	or Description / Con	nment Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 In	sulation	Floor Insulation Fiberglass Batts	- 4	756					
2 La	abor	Floor Insulation Fiberglass Batts	- 4- 4	756					
Othe	er Detail								
				Measur	e Sub Total:			Sub Total:	
Fie	ld Notes:				*******				

ħ.	fleasure 4 DWF	Tank Insulation			Componen	ts			Inspected
Co	omment extend p	ressure relief pipe as ne	eded		•				
					Estimated	1		Actual	I
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.						J (1	
2	Labor	DHW Tank Insulation	Each	1		N			
Ot	her Detail								
L_						¥4.00.4			
									77.4
				Measur	Sub Total:		]	Sub Total:	
F	Fleld Notes:	///		*****	1000				
ŧ									
	7/4								

Page 5 of 7

	Measure 5 CO	Monitor is Needed			Componen	ts			Inspected
C	<b>Comment</b> Refer to Field Gu	Attachment A- Standar uide.	ds for Wea	theriza	ation Materia	ls and So	outheas	t	
ш					Estimated			Actual	
Ħ	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.	}						,,,
2	Labor	Labor	Each	1					
(	Other Detail					•			
				Measur	e Sub Total:		S	ub Total:	
		or Barrier Needed			Component	s			nspected
C	<b>omment</b> Must be walls and earth. Mo	ement/CrawIspace)(Q 6 mil poly. Must be insta d support piers. Must be ust be secured at all sea ization Materials and Sc	alled 100% securely f ams. Refer	astene to Atta	ed. Must be o schment A- S	leated do	own to		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Basement /Crawlspace Vapor Barrier	SqFt	756				7811	
2	Labor	Labor	SqFt	756					1
0	ther Detail								L
				leasure	Sub Total:		] Sı	ıb Total:	
	Fleld Notes:	1994							

Client Name:

Client ID: 80008KN0166

Alt. Client ID: KNOX

Work Order (Bid Form)

Work Order Name: WO/80008KN0166/1 Report Run On: 5/8/2010 DOE Weatherization Assistant

Version 8.6.0

Page 6 of 7

|--|

Client Name:

Client ID: 80008KN0166 Alt. Client ID: KNOX Work Order (Bld Form)

Work Order Name: WO/80008KN0166/1 Report Run On: 5/8/2010

Page 7 of 7